

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

British Aerospace Regional Aircraft Limited (Formerly British Aerospace Commercial Aircraft Limited, Vickers-Armstrongs Aircraft Limited): Docket 94-NM-166-AD.

Applicability: All Model Viscount 744, 754D, and 810 airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent cracking or corrosion of the main spar forward booms or the upper root joint attachment fitting, which consequently could lead to the failure of the tailplane assemblies and reduce the controllability of the airplane, accomplish the following:

(a) Prior to the accumulation of 8 years of service since date of manufacture of this airplane, or within 18 months after the effective date of this AD, whichever occurs later, perform an inspection to detect corrosion of the tailplane assemblies, in accordance with British Aerospace Regional Aircraft Limited Viscount Alert Preliminary Technical Leaflet (PTL) 182, Issue 2, dated August 7, 1992 (for Model Viscount 810 airplanes), or Viscount PTL 313, Issue 2, dated February 1, 1993 (for Model Viscount 744, 754D, airplanes), as applicable. If corrosion is detected during the inspection, prior to further flight, correct the discrepancies in accordance with the service bulletin. Thereafter, repeat the inspection at intervals not to exceed 8 years.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 13, 1995.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-9624 Filed 4-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 94-NM-112-AD]

Airworthiness Directives; British Aerospace Model Viscount 744, 745D, and 810 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all British Aerospace Model Viscount 744, 745D, and 810 airplanes. This proposal would require an inspection of certain fittings of the engine mount structure to determine whether fasteners have been installed in inspection holes and to determine whether those holes are oversized. It would also require various follow-on actions, depending upon the results of the inspection. This proposal is prompted by reports indicating that fasteners were installed in the inspection hole of the engine "W" frame socket fittings and the inspection hole was oversized due to fatigue cracking. The actions specified by the proposed AD are intended to prevent such fatigue cracking, which could lead to failure of the fasteners and consequent separation of the engine from the airframe.

DATES: Comments must be received by May 30, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-112-AD, 1601 Lind Avenue SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from

British Aerospace Regional Aircraft Ltd., Engineering Support Manager, Military Business Unit, Chadderton Works, Greengate, Middleton, Manchester M24 1SA, England. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1320.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94-NM-112-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 94-NM-112-AD, 1601 Lind Avenue SW., Renton, Washington 98055-4056.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on certain British Aerospace

Model Viscount 744, 745D, and 810 airplanes. The CAA advises that it has received a report indicating that drive screws were installed in the inspection hole of engine "W" frame socket fittings. Investigation revealed that these drive screws were installed in accordance with Gulfstream Customer Bulletin No. 241C. However, the fitting of the drive screws into the inspection holes has caused fatigue cracking. In another report, the inspection hole was oversized in excess of the original 0.125-inch diameter; with such oversizing of the inspection hole, the fitting is susceptible to the problems associated with premature fatigue cracking. These conditions, if not detected and corrected in a timely manner, could lead to failure of the fitting and consequent separation of the engine from the airframe.

British Aerospace has issued Preliminary Technical Leaflet (PTL) 501, dated May 1, 1994, which describes procedures for performing a detailed visual inspection of "W" frame socket fittings of the engine mount structure to determine whether drive screws or blind rivets have been installed in inspection holes, and to determine whether those holes are oversized. The PTL also describes various follow-on actions, including a nondestructive test (NDT) to detect discontinuity (i.e., cracks, corrosion, and mechanical damage) of holes, rework of the hole, and replacement of the "W" frame fitting with a new or serviceable part. The CAA classified this PTL as mandatory.

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require performing a detailed visual inspection of "W" frame socket fittings of the engine mount structure to determine whether drive screws or blind rivets have been installed in inspection holes and to determine whether those holes are oversized. It would also require

various follow-on actions, depending upon the results of the inspection. The actions would be required to be accomplished in accordance with the PTL described previously.

As a result of recent communications with the Air Transport Association (ATA) of America, the FAA has learned that, in general, some operators may misunderstand the legal effect of AD's on airplanes that are identified in the applicability provision of the AD, but that have been altered or repaired in the area addressed by the AD. The FAA points out that all airplanes identified in the applicability provision of an AD are legally subject to the AD. If an airplane has been altered or repaired in the affected area in such a way as to affect compliance with the AD, the owner or operator is required to obtain FAA approval for an alternative method of compliance with the AD, in accordance with the paragraph of each AD that provides for such approvals. A note has been included in this notice to clarify this long-standing requirement.

The FAA estimates that 29 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 25 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$43,500, or \$1,500 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft

regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

British Aerospace Regional Aircraft Limited (Formerly British Aerospace Commercial Aircraft Limited, Vickers-Armstrongs Aircraft Limited): Docket 94-NM-112-AD.

Applicability: All Model Viscount 744, 745D, and 810 airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking, which could lead to the possible separation of the engine from the airframe, accomplish the following:

(a) Within 12 months after the effective date of this AD, perform a detailed visual inspection of "W" frame socket fittings of the engine mount structure to determine whether drive screws or blind rivets have been installed in inspection holes and to determine whether those holes are oversized,

in accordance with the Accomplishment Instructions, section 2.1 PART ONE, paragraphs A., B., C., D., E. and F., of British Aerospace Preliminary Technical Leaflet (PTL) 501, dated May 1, 1994.

(b) If drive screws or blind rivets are found installed, or if the inspection holes are found to be oversized, during the inspection required by paragraph (a) of this AD, at the next scheduled engine removal, but no later than 12 months after the effective date of this AD, perform a nondestructive test (NDT) to detect discontinuities (i.e., cracks, corrosion, and mechanical damage) at inspection holes; rework the hole or replace the "W" frame fitting with a new or serviceable part; and perform the specified follow-on actions; in accordance with the Accomplishment Instructions, section 2.2 PART TWO, paragraphs A., B., C., D., E., and F., of British Aerospace Preliminary Technical Leaflet (PTL) 501, dated May 1, 1994.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 13, 1995.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95-9625 Filed 4-18-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 94-ACE-17]

Proposed Amendment to Class E Airspace; Washington, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area at Washington, IA. The development of a new standard instrument approach procedure (SIAP) at Washington Municipal Airport, Washington, IA, has made the proposal necessary. The intended effect of this proposal is to provide controlled airspace for aircraft executing the SIAP at Washington, IA.

DATES: Comments must be received on or before May 30, 1995.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Air Traffic Operations Branch, ACE-530, Federal Aviation Administration, Docket No. 94-ACE-17, 601 East 12th Street, Kansas City, MO 64106.

The official docket may be examined in the Office of the Assistant Chief Counsel for the Central Region at the same address between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

An informal docket may also be examined during normal business hours in the office of the Manager, Air Traffic Operations Branch, Air Traffic Division, at the address listed above.

FOR FURTHER INFORMATION CONTACT: Kathy Randolph, ACE-530c, Federal Aviation Administration, 601 East 12th Street, Kansas City, Missouri 64106; telephone: (816) 426-3408.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Docket No. 94-ACE-17." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM)

by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-230, 800 Independence Avenue SW., Washington, DC 20591, or by calling (202) 267-3484.

Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A, which describes the application procedures.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to provide additional controlled airspace for a new Instrument Flight Rules (IFR) procedure at the Washington Municipal Airport. The additional airspace would segregate aircraft operating under VFR conditions from aircraft operating under IFR procedures. The area would be depicted on appropriate aeronautical charts thereby enabling pilots to circumnavigate the area or otherwise comply with IFR procedures. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9B, dated July 18, 1994, and effective September 16, 1994, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal